

FOOTWEAR




Fig. 1

0901310-100301




Fig. 2




FIG. 3A




FIG. 3B

FIG. 4




FIG. 4






Fig. 5

FOUO "OFET0660



6A


SEM Micrograph of Group B at 300x after Electrochemical Test.



6B

SEM Micrograph of Group B at 700x after electrochemical test.

105007 07E10660



7A




7B

SEM micrographs of the Hayes CrCoMo sample after ASTM F746 corrosion test indicates intergranular corrosion attacks.

105007 07ET0660



7C




7D


SEM micrographs of the Hayes CrCoMo sample after ASTM F746 corrosion test exhibiting corrosion attacks.



105001" 01E10660



8A



8B

SEM micrographs of the Hayes CrCo sample prior to any corrosion test.